



# **MACCHINE A CALETTARE ACCESSORI**

SHRINK FIT MACHINE  
ACCESSORIES

# **5B**



# MACCHINE A CALETTARE ACCESSORI

## SHRINK FIT MACHINE ACCESSORIES




**BARRA DI CONTROLLO**  
TEST ARBOR

**5B**

**Barre di controllo con certificato HSK**

Test arbor with accuracy certificate HSK




**HSK63A**

CODICE	FAM	D	FORMA	H	EUR
HSK63A.H335.CK40	1	40	HSK63-A	335	
HSK100A.H335.CK50		50	HSK100-A	335	
HSK63F.H335.CK40		40	HSK63-F	335	

**Barre di controllo con certificato MAS/403BT**

Test arbor with accuracy certificate MAS/403BT




**BT30 / 40 / 50**

CODICE	FAM	CK	FORMA	H	EUR
BT30.H237.CK32	1	32	AD	237	
BT40.H335.CK40		40	AD	335	
BT50.H340.CK50		50	AD	340	

**Barre di controllo con certificato DIN/69871**

Test arbor with accuracy certificate DIN/69871



**TC30 / 40 / 50**

CODICE	FAM	CK	FORMA	H	EUR
TC30.H237.CK32	1	32	AD	237	
TC40.H335.CK40		40		335	
TC50.H340.CK63		63		340	