



**MANDRINI ATTACCO
CONO MORSE DIN/228 E DIN/238**

MORSE TAPER COLLET CHUCKS
DIN/228 AND DIN/238

3G


MANDRINI ATTACCO CONO MORSE DIN/228 E DIN/238

MORSE TAPER COLLET CHUCKS
DIN/228 AND DIN/238




MANDRINI A CAMBIO RAPIDO QC
QC QUICK CHANGE TAPHOLDERS


3G

Mandrini a cambio rapido
 Quick - change tapholders

TIPO - B

CODICE	CR	CM	D	L	EUR
CM2B-QC2	QC2	CM2B	50	75	
CM3B-QC2	QC2	CM3B	50	75	
CM3B-QC3	QC3	CM3B	60	88	
CM4B-QC3	QC3	CM4B	60	88	
CM4A-QC3	QC3	CM4A	60	88	

Bussole a cambio rapido cono morse
 Quick - change morse taper adapters

QC


CODICE	CR	CM	D	L	EUR
QC2-CM1B	QC2	CM1B	42	18.0	
QC2-CM2B	QC2	CM2B	42	30.5	
QC3-CM1B	QC3	CM1B	50	20.5	
QC3-CM2B	QC3	CM2B	50	20.5	
QC3-CM3B	QC3	CM3B	50	38.5	

Bussole a cambio rapido a compensazione assiale in compressione e trazione
 Quick - change tapping adapters Tension/Compression

QC

CODICE	CAP	CR	X	D	L	T	C	EUR
QC2-TC1	M3 ÷ M12	QC2	19	36	42	7.5	7.5	
QC2-TC2	M8 ÷ M20	QC2	31	53	72	12.5	12.5	
QC3-TC1	M3 ÷ M12	QC3	19	36	72	7.5	7.5	
QC3-TC2	M8 ÷ M20	QC3	31	53	66	12.5	12.5	
QC3-TC3	M14 ÷ M33	QC3	48	78	126	20	20	

Bussole a cambio rapido tipo B


Quick change drill chuck adapters B


QC

CODICE	CR	RIDUTTORE	D	L	EUR
QC2-B16	QC2	B16	42	23	
QC3-B16	QC3	B16	50	25.5	

Bussole a cambio rapido Portapinze

Quick change collet adapters


QC

CODICE	CAP	CR	Pinza	D	L	L1	EUR
QC2-ER16	0.5 ÷ 10	QC2	ER16	32	42	30 ÷ 50	
QC3-ER32	1.0 ÷ 16	QC3	ER32	50	51	40 ÷ 60	